
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-029654 Address: 333 Burma Road **Date Inspected:** 05-Jun-2013

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: **USA Hoist Location:** Crest Hill, IL

CWI Name: Robert Zimny **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** SAS Tower Elevator

Summary of Items Observed:

Caltrans Office of Structural Material (OSM) Quality Assurance Inspector (QAI) Joselito Lizardo was present at USA Hoist, Crest Hill, IL as requested to perform observations on the welding of components for the San Francisco Oakland Bay Bridge (SFOBB) Project.

At USA Hoist assembly shop, this QA randomly observed USA certified welder Manolo Luna who took over from Matt Wasiqi perform 2F (horizontal) position gas shielded Flux Cored Arc Welding (FCAW-G) welding 1/4" fillet repair between 1 34" diameter x 7/8" thick rack pad to 6" x 6" x 3/8" thick tube steel tower mast. The welder was noted using gas shielded FCAW-G with 1.1mm E71T-1C/M-H8 Familiarc DW-50 wire electrode implementing USA Hoist Welding Procedure Specification FCAW 3210. The shielding gas being used was noted a combination of 75% Argon and 25% CO2 with flow rate of 40 CFH. During the shift, the working welding parameters was measured 27 volts and 200 amperes which deemed in compliance to the project requirements. At the end of the shift, fillet welding repair on the undersize 1/4" fillet all around the rack pad was still continuing on various tower steel masts and should remain tomorrow.

At the same shop, this QA randomly observed USA Hoist welder Matt Wasiqi perform 1F fillet welding between the 4 ½" x 3' x 3/8" thick stiffener plate and 5" x 3 ½" x 1/2" thick bent plate rear tie in bracket. The ¼" fillet weld is being welded per USA shop drawing 914204-11. The welder was noted using gas shielded FCAW-G with 1. 1mm E71T-1C/M-H8 Familiarc DW-50 wire electrode implementing USA Hoist Welding Procedure Specification FCAW 3210. The shielding gas being used was noted a combination of 75% Argon and 25% CO2 with flow rate of 35 CFH. During the shift, the working welding parameters were measured 29 volts and 230 amperes which deemed in compliance to the project requirements. At the end of the shift, 1/4" fillet welding on all sides of the

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

stiffener plate to the rear tie in bracket was still continuing and should remain tomorrow.





Summary of Conversations:

No significant conversation occurred today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact SMR Gary Thomas 916-764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Lizardo, Joselito	Quality Assurance Inspector
Reviewed By:	Foerder, Mike	QA Reviewer